

METHODS AND OBJECTIVES OF THE STRUCTURAL ASSESSMENT OF HISTORIC CONSTRUCTIONS GENERAL ASPECTS AND CASE STUDIES


Speaker: Prof. Eng. Claudio Modena




INGEGNERIA CIVILE,
EDILE E AMBIENTALE
CIVIL, ARCHITECTURAL AND
ENVIRONMENTAL ENGINEERING



SEISMIC BEHAVIOR OF MASONRY BUILDINGS



- Disconnected walls (isolated wall)
- High stiffness floor
- Link wall-wall and wall-floor with tie-beam



BOX BEHAVIOR:

Horizontal forces absorbed by the walls in their plane

- Sufficiently rigid deck
- Adequate connection between walls
- Link wall-floor and wall-roof



(ZAG Slovenia, M. Tomazevic)




INGEGNERIA CIVILE,
EDILE E AMBIENTALE
CIVIL, ARCHITECTURAL AND
ENVIRONMENTAL ENGINEERING





Provided that adequate masonry quality is ensured - in case using appropriate repair/strengthening techniques –most of the stability problems are connected to equilibrium considerations.

Main causes:

- Lack of connection between walls
- Lack of connection between walls and floors
- Reduced in plane stiffness of floors
- Masonry composition
- Existing crack pattern



Giuffrè, 1993

Salò-Garda lake
earthquake (24/11/2004)

Case studies




THE CHURCH OF 'MADONNA DEL PIANTO' (Padova)




XVIII Century church by Frigimelica with central plan and some irregularities due to following resets done in the first half of the XX Century


CURRENT CONDITION



CRITICAL SURVEY



MACROELEMENTS








Seismic Risk Preparedness and Mitigation of Culture Heritage Sites

מוכנות והיערכות לסיכון רעידות אדמה באתר מורשת תרבותית


ישראל, ירושלים, ינואר 19-20, תשע"ד

LATERAL CHAPELS



POSSIBLE AND PROBABLE COLLAPSE MECHANISMS



FAÇADE



$$M_{st1} = 52230 \text{ daNm}$$

$$M_{inst1} = 3984900 \text{ daNm}$$



$$\lambda_1 = 0,0131$$



$$M_{st1} = 236220 \text{ daNm}$$

$$M_{inst1} = 4441250 \text{ daNm}$$


$$\lambda_1 = 0,05319$$



$$M_{st1} = 41137 \text{ daNm}$$

$$M_{inst1} = 1473034 \text{ daNm}$$

$$\lambda_1 = 0,0279$$



$$M_{st1} = 2125 \text{ daNm}$$


$$M_{inst1} = 148300 \text{ daNm}$$

$$\lambda_1 = 0,0143$$



INTERVENTIONS

ROOF BRACING

Between 2003 and 2004 some interventions were carried out. Bracings were installed on the roof above the façade. This has significantly improved the seismic response of this element, as shown by the increase of the collapse coefficient for the overturning of the façade.



Confronto tra i valori dei coefficienti di collasso dei meccanismi di ribaltamento della facciata con e senza i controventi di falda





SPANISH FORTRESS – L'AQUILA



Seismic Risk Preparedness and Mitigation of Culture Heritage Sites

מוכנות והיערכות לסיכון רעידות אדמה באתר מורשת תרבותית

ישראל, ירושלים, ינואר 19-20, תשע"ד



Muratura in pietrame con elementi di pezzatura disomogenea, parzialmente sbozzati

Muratura in pietra squadrata

Muratura a sacco con paramento esterno in travertino



INGEGNERIA CIVILE,
EDILE E AMBIENTALE
CIVIL, ARCHITECTURAL AND
ENVIRONMENTAL ENGINEERING






DANNI PRINCIPALI:

- ribaltamento fuori-piano e meccanismi flessionali nelle pareti;
- rotture a taglio nei muri;
- danni ad archi e volte;
- crolli locali di solai e volte.



Corpo Sud-Est



Crollo parziale della sommità della parete laterale e della copertura



Cattiva qualità della muratura e cattivo ammorsamento tra pareti. Rivestimento esterno in travertino.

Presenza di cordoli in c.a. e solai in latero-cemento, hanno portato ad un appesantimento ed martellamento della muratura



INGEGNERIA CIVILE,
EDILE E AMBIENTALE
CIVIL, ARCHITECTURAL AND
ENVIRONMENTAL ENGINEERING






Caratteristiche scadenti delle murature



Corpo Sud-Est



Ribaltamento del loggiato e dei piloni del piano terra




Il porticato a doppia loggia. Individuazione della lesione.


Seismic Risk Preparedness and Mitigation of Culture Heritage Sites

מוכנות והיערכות לסיכון רעידות אדמה באתר מורשת תרבותית

ישראל, ירושלים, יט' בשבט, תשע"ד 19-20 January 2014



0





Point 1

State of stress



2.47 N/mm²




Point 2

State of stress




1.82 N/mm²



MARTINETTI PIATTI DOPPI





Martinetto piatto doppio – CA-J3D



Seismic Risk Preparedness and Mitigation of Culture Heritage Sites
מוכנות והיערכות לסיכון רעידות אדמה באתר מורשת תרבותית
ירושלים. יח'-יס' בשבט, תשע"ד 19-20 January 2014


TERMOGRAFIE



CA-T2

RADAR

Profilo su pilastro 1 con antenna da 200MHz




Sono state eseguite prove radar sui pilastri danneggiati per studiare la morfologia della sezione. Si nota il diverso spessore delle pietre.

Si stanno ancora elaborando i risultati





TOMOGRAFIE SONICHE

Le prove soniche sono state eseguite su due pilastri della fortezza: uno danneggiato dal terremoto, l'altro invece intatto.




TOMOGRAFIE SONICHE

Le prove soniche sono state eseguite su due pilastri della fortezza: uno danneggiato dal terremoto, l'altro invece intatto.





a) b)



Griglia dei punti di acquisizione



SONIC TOMOGRAPHY



La terza tomografia è stata condotta su una parete muraria nell'ala sud-est del castello. Lo scopo prefisso è stato quello di raccogliere dati qualitativi sulla muratura di questa area della fortezza pesantemente danneggiata dal sisma.




Seismic Risk Preparedness and Mitigation of Culture Heritage Sites

מוכנות והיערכות לסיכון רעידות אדמה באתר מורשת תרבותית


ישראל, ירושלים, ינואר 19-20, תשע"ד



PILASTRO DANNEGGIATO



PILASTRO INTEGRO





TOMO 1

ICEA
EDILE E AMBIENTALE
CIVIL, ARCHITECTURAL AND
ENVIRONMENTAL ENGINEERING





La tomografia della parete spessa mostra una distribuzione omogenea delle velocità soniche attraverso lo spessore. La muratura, anche all'interno del muro, è di buona qualità




ישראל, ירושלים, ינואר 19-20, תשע"ד

SISTEMA DI MONITORAGGIO STATICO



SISTEMA DI MONITORAGGIO STATICO


Maggio 2009 rappresentazione delle magnitudo (IGNV) e i rilevamenti dei fessurimetri il giorno 15 maggio Sono stati applicati i tiranti e si giustifica il salto (chiusura della fessura).




Maggio 2009 rappresentazione delle magnitudo (IGNV) e i rilevamenti dei fessurimetri. Il mese è suddiviso due momenti prima dei tiranti. (06-15/05)



FASE 1



FASE 2



corrente
di carico


posizionamento tiranti

corrente
di carico


iniezione con malte antiritiro
a base di calce idraulica

iniezione con malte antiritiro
a base di calce idraulica

FASE 3




FASE 4



Il progetto di recupero dei pilastri
prevede il taglio alla base degli stessi
per «ri-centrare» il carico,
attualmente eccentrico a causa del
meccanismo di ribaltamento della
parete, che ha determinato lo
schiacciamento della base degli stessi.


taglio con lama
diamantata di piccolo
spessore su giunto
orizzontale

iniezione con malte
antiritiro a base di
calce idraulica



Problematiche rispetto al posizionamento dei tiranti:

- Assenza di allineamento tra setti murari e pilastri
- Limitato spessore tra pavimento e estradosso della volta




Seismic Risk Preparedness and Mitigation of Al-Asudet Site העמידה והיערכות לסיכון רעידות אדמה באתר מורשת תרבותית


ישראל, ירושלים. י'ח-ט' תשע"ד, 19-20 January 2014

Al-Asudet progetto d'interventi POSIZIONAMENTO DEI TIRANTI


VISTA DALL'ALTO GIUNZIONE PIATTI




Creazione di un sistema «reticolare» per consentire lo sfalsamento dei tiranti.



VISTA LATERALE



SEZIONE 1-1'



Tra le principali problematiche connesse alla ricostruzione di strutture gravemente danneggiate vi è la presenza di murature con caratteristiche meccaniche scarse o addirittura pessime.


Si pone quindi il problema di trovare una tipologia costruttiva che garantisca delle buone proprietà meccaniche di resistenza e coesione e al tempo stesso rispetti la tradizione costruttiva originaria.



PROGETTO DI RICOSTRUZIONE:
utilizzo di ricorsi in mattoni con armature inserite nei giunti



RICORSO DI MATTONI

ARMATURA NEI GIUNTI -
BARRE Ø6 mm



Seismic Risk Preparedness and Mitigation of Culture Heritage Sites


מוכנות והיערכות לסיכון רעידות אדמה באתרי מורשת תרבותית



PALAZZO DELLA RAGIONE (Padova – Italy)





The building was the City Council Palace of Padova (Italy). Its construction started in 1218.



PALAZZO DELLA RAGIONE (Padova – Italy)

The roof covers a unique, skewed room, approximately 28 m wide and 80 m long, formed by slender ribs (36x40 cm², obtained by joining curved boards 12 cm thick, whose length varies from less than one meter to three meters), which 3 cm thick boards are simply nailed to.





PALAZZO DELLA RAGIONE (Padova – Italy)

OPTIMIZING THE INTERVENTIONS: INVESTIGATIONS AND MONITORING

Two different type of investigations were adopted to analyze the static and dynamic effects of the wind on the roof shell:

- on-site measurement of the wind pressure;
- wind tunnel testing of a scaled-model of the building and the surrounding portion of the historical centre.

Scaled model for the wind tunnel testing




Positioning of the wind pressure transducers

PALAZZO DELLA RAGIONE (Padova – Italy)



Idea:



- monitoring of the wind effects
- stepped sine test
- FE modeling
- identificazione modale
- on-line data management



Data acquisition

www database

Web monitoring home page



Modal analysis



INGEGNERIA CIVILE,
EDILE E AMBIENTALE
CIVIL, ARCHITECTURAL AND
ENVIRONMENTAL ENGINEERING



PALAZZO DELLA RAGIONE (Padova – Italy)

TYING OF A CRACKED PILLAR



Provisional intervention

Final intervention



PALAZZO DELLA RAGIONE (Padova – Italy)



Deterioration of the internal part of a rib

The design of the local repairing was made by taking simple temporary measures allowing for maintaining the stable 3D behaviour and inhibiting local buckling in any phase of the works, by simply limiting the removal (when needed) of the boards forming the shell very locally, in order to permit local repairing, and through simple lateral supports.




Deterioration of a shelf



Affected top of a rib

PALAZZO DELLA RAGIONE (Padova – Italy)

INTERVENTION ON THE RIBS



1) lateral bracing of the ribs



2) insertion of a temporary steel tie



3) carrying out a metallic stirrup

PALAZZO DELLA RAGIONE (Padova – Italy)

INTERVENTION ON THE RIBS



Substitution of degraded elements



Local stitching of cracks



Restoration and integration of the nails


PALAZZO DELLA RAGIONE (Padova – Italy)

INTERVENTION ON THE SHELVES

Removal of the deteriorated portion of the shelf and back-blocking of the rib

PARTICOLARE - RIPRISTINO CONTINUITÀ DEL DORMIENTE
Esempio di Soluzione (costolone n°9)


taglio della porzione posteriore ed inserimento di
un dormiente posteriore continuo



Restoration

Dormiente anteriore degradato da sostituire (durante
l'operazione il carico verrà trasferito al dormiente
posteriore mediante cuneo e controcuneo)


ove possibile verranno rispettate le
giunzioni esistenti





Substitution



Investigation and monitoring for the design of a strengthening intervention on the Basilica dei Frari – Venice



Basilica dei Frari (Venice)




1st PHASE (1361-1396): CONSTRUCTION OF THE BELL TOWER

The tower, built next to the church between 1361 and 1396, was originally conceived as a completely independent structure.


It is 65m tall, has a square base of about 9.5m and shows a double pipe brick masonry structure, supporting the internal staircase.

Basilica dei Frari (Venice)



1902: COLLAPSE OF THE BELL TOWER OF THE ST. MARK BASILICA

STRUCTURAL
INTERVENTION IN THE
20TH CENTURY



Monitoring of the venetian towers, including the “Frari” bell tower


RESULTS OF THE MONITORING:

- Differential settlement between church and tower: 30 cm
- Out-of-plumb: 76cm on a height of 42.5m

1903: Intervention on tower's foundations

CONSEQUENCES:

- Reverse of tower's rotation toward the church
- The new structural configuration caused the formation of widespread cracks and extensive damages on structural elements of the church directly connected to the bell tower



INGEGNERIA CIVILE,
EDILE E AMBIENTALE
CIVIL, ARCHITECTURAL AND
ENVIRONMENTAL ENGINEERING





Experimental investigations and monitoring

1990

- fotogrammetric survey;
- geotechnical investigations on the foundation's soil;
- endoscopies;
- single and double flat-jack tests on the masonry elevation structures;
- sonic tests on steel ties;
- monitoring of the main cracks, by means of extensometers;
- positioning of clinometers (detection of rotations of the bell-tower).



discrete stability of the tower structure; out of plumb of about 0.8 m

2000

- worrying sign of structural deterioration (new crack patterns; widening of already existing fissures; falling of small portions of plaster and bricks from the vaults).
- survey of differential settlements in different points of the complex



disconnectedness of the stone ashlars of the aisle arch adjacent to the bell-tower (differential settlement of the arch supports) → installation of a timber prop

average subsidence of the structure of the church:


average subsidence of the area of the bell-tower base:

- 10 ÷ - 20 mm


- 49.8 mm East corner

- 61.3 mm South corner


- 93.3 mm West corner




XV




XV-XX



XX-XXI



The differential settlements and the comparison between the photogrammetric survey of 1995 and 2000, indicated that **the bell-tower is tilting in the opposite direction respect the "historical" tendency**, meaning that it is going back towards its vertical.



0 2.5 5m

A : long-base extensometers
B : crack-gauges

2001

automatic monitoring system (check of the deformations):


- **6 long base extensometers** relative displacements between the walls of the bell-tower and the adjacent structures of the basilica;
- **8 crack-gauges** installed on the main cracks of the South-West side of the bell-tower and of the wall above the stone arch.




the opening of the cracks is only partly caused by the settlement noticed at the foundations level

2003 investigation campaigns




ANALYSIS OF THE STATE OF STRESS: FLAT JACK TESTS



2003 extension of the automatic monitoring system




- Direct Pendulum
- Crack-gauges
- Strain Gauges
- Temperature sensors





2003 extensive geotechnical investigation campaign

- analysis of the **subsoil stratigraphy and geotechnical properties**;
- exploration of the exact geometry and typology of the **foundation block**;
- definition of an accurate **geotechnical model** of the foundation finally completed;
- **in situ tests**:



- **2 vertical boreholes**: outside the church, to a depth of 5.50 m and inside the bell-tower, to a depth of 21.50 m;
- **5 inclined boreholes**;
- **4 continuous borings** into the foundation block:
 - EI1 and EI2 inclined of 30°, drilled for length of 4 m and located inside the basilica;
 - SVE1 and SVE2 short vertical borings, carried out on the NE side of the bell-tower;
- **4 static penetrometer tests** with monitoring of pore water pressure (piezocone tests – CPTU) pushed to variable depths (17.00 ÷ 19.20 m);
- **Standard Penetration Tests (SPT)**, in boreholes;
- **Extractions** of soil and foundation samples.

Geotechnical section and foundation geometry



Origin of continuous settlements and stability problems

Some **progressive failure of the soft silty clay layer**, squeezed between the piles end and the unit C, must be taken into account.

In addition, a **possible increasing decay of the mechanical characteristics of the wooden piles** under the foundation block could also be seen as concomitant cause.

Structural modeling



The modelled portion of structure includes the **bell-tower and the adjoining parts of the church** that were mostly affected by the interaction with the tower.



The only load condition considered is the **self weight**. The load corresponding to some parts of the real structure not modelled (timber structure roof of the basilica, belfry), was imposed as external forces; the crossed vaults' filling was included as surface load.

The **mechanical properties** chosen to describe the materials arise from the results of previous tests performed on the masonry structures. In particular:

- **elastic modulus** $E = 3300 \text{ MPa}$ (average of the results of double flat jack tests performed on the bell-tower masonry)
- **density** $\rho = 2000 \text{ kg/m}^3$

The material is considered homogeneous and isotropic, and the analyses performed are linear elastic.






Two **previous models**, calibrated with the available experimental data (historical drawings, surveys, monitoring and on site tests), were analyzed before implementing the actual one, by means of imposed rotations and translations at the base of the bell-tower:

- after the construction (1450);
- before the strengthening intervention on the bell-tower (1903).


In each model, after running the analysis, a higher deformability was assigned to the elements subjected to an excessive tension respect the assumed strength of the material, in the successive analysis.

A **tensile stress concentration** appeared in the model where a **real crack pattern** is evident. The propagation of some principal cracks was followed by the subsequent iterative process.








The **final model** reflects the tendency of the XX century. An “inverted” rotation was imposed to the bell-tower, with an average settlement of 84 mm.

Results:




- preferential channels of **compressive stress** localized inside the masonry wall above the propped arch;
- high **tensile stresses** found in the same masonry wall, due to the settlements of the bell-tower → wide crack patterns and loss of shape of the stone arch;
- high **stress** found below the capital of the column → horizontal thrust determined by the movements of the bell-tower;
- **tensile stress** in correspondence of the bell-tower window opening on the transept → presence of the main fissure on the external pipe of the bell-tower.



The differential settlements and the comparison between the photogrammetric surveys, indicated that **the bell-tower is tilting in the opposite direction respect the “historical” tendency**, meaning that it is going back towards its vertical.

- preferential channels of **compressive stress** localized inside the masonry wall above the propped arch;
- high **tensile stresses** in the same masonry wall → wide crack patterns and loss of shape of the stone arch;
- **high stress** below the capital of the column → horizontal thrust determined by the movements of the bell-tower;
- **tensile stress** in correspondence of the bell-tower window opening on the transept → presence of the main fissure on the external pipe of the bell-tower.

Structural Diagnosis





CONSEQUENCES OF THE INTERNAL STATE OF STRESS CREATED BY THE MECHANICAL INTERACTION:

increase of the compression load on the column

a strong transverse bending stress on the column, due to both the eccentricity of the vertical load applied to it and the horizontal component of the thrust


decrease of the vertical load (equal to the increase on the column) on the tower








BASIC PRINCIPLE OF THE INTERVENTION:

- Creation of a joint in order to separate the bell tower from the church and make them structurally more independent
- Reduction of the compressive forces that transfer part of the tower's self weight to the column



CIVIC THEATRE – SCHIO (VI)


Morphology



Ridotto



Platea



Liv. 04: 215.76 s.l.m.m.

Palcoscenico

Liv. 03: 208.33 s.l.m.m.

Liv. 02: 205.90 s.l.m.m.

Liv. 01: 203.00 s.l.m.m.

Liv. 00: 199.50 s.l.m.m.

Liv. - 01: 197.26 s.l.m.m.


Liv. - 02: 196.26 s.l.m.m.



CIVIC THEATRE – SCHIO (VI)

Structures


- foundations:
 - stone, $h \geq 1.50$ m
- vertical structures:
 - masonry walls
 - RC columns → Hennebique system
- horizontal structures:
 - beams and floors → Hennebique system
- roof structures:
 - timber trusses



Baice, 1993



CIVIC THEATRE – SCHIO (VI)

Hennebique system




CIVIC THEATRE – SCHIO (VI)

Hennebique system



Porcheddu archive, Torino




Porcheddu archive, Torino




CIVIC THEATRE – SCHIO (VI)

Investigation campaign



CIVIC THEATRE – SCHIO (VI)

Geotechnical investigations



CIVIC THEATRE – SCHIO (VI)

Investigations in situ on masonry walls



CIVIC THEATRE – SCHIO (VI)

Investigations in situ on RC elements



CIVIC THEATRE – SCHIO (VI)

Interventions


- rehabilitation of vertical masonry structures
- retrofitting of RC structures
- strengthening of existing stairways
- retrofitting of roof structures

CIVIC THEATRE – SCHIO (VI)

Interventions

Rehabilitation of vertical masonry structures:

- ‘scuci-cuci’ technique
- injections of slurries based on hydraulic lime
- repointing of joints after elimination of degraded mortar
- wall reconstructions in correspondence of vertical cavities




Strengthening intervention on masonry walls using reinforcement bars with a small diameter

CIVIC THEATRE – SCHIO (VI)


Interventions

Retrofitting of RC structures:


- 3D FEM model



Mesh



Bending moment



Shear



INGEGNERIA CIVILE,
EDILE E AMBIENTALE
CIVIL, ARCHITECTURAL AND
ENVIRONMENTAL ENGINEERING




CIVIC THEATRE – SCHIO (VI)

Interventions

Retrofitting of RC structures:

- strengthening detail with a RC slab





CIVIC THEATRE – SCHIO (VI)


Interventions

Retrofitting of RC structures:


- strengthening detail of beam with FRP



VISTA "A" - DESCRIZIONE DELLE FASI OPERATIVE



a) inserimento dei filamenti di fibra di carbonio arrotolati attraverso due fori di piccolo diametro praticati sulla soletta in c.a. e apertura a ventaglio degli stessi a contatto con l'estradosso della soletta.




b) incollaggio della fascia superiore (n°1 strato 10x30cm) per l'ancoraggio dei filamenti all'estradosso della soletta in c.a.

INDICAZIONI OPERATIVE:

- pulizia e regolarizzazione della superficie;
- eventuale applicazione del primer;
- eventuale applicazione della rasatura;
- applicazione dell'adesivo tipo CARBOSTRU® AD;
- applicazione della fascia in tessuto unidirezionale in fibra di carbonio tipo CARBOSTRU® UDHR 800 o equivalente;
- applicazione dello strato finale di adesivo.

NOTA: rispettare in ogni caso le indicazioni riportate nella documentazione tecnica del produttore.

Carbon fiber fabric



CIVIC THEATRE – SCHIO (VI)

Interventions


Retrofitting of RC structures:

- local FEM model

Finite Element Model

Maximal bending moment
100 cm²


100000
80000
60000
40000
20000
0



x-x bending moment


Maximal vertical displacement
100 cm²

100000
80000
60000
40000
20000
0




nodal vertical displacement

slab thickness = 12 cm



Strengthening interventions



Scarifica e cappa integrativa

fasce di tessuto FRP all'estradosso



INGEGNERIA CIVILE,
EDILE E AMBIENTALE
CIVIL, ARCHITECTURAL AND
ENVIRONMENTAL ENGINEERING




CIVIC THEATRE – SCHIO (VI)

Interventions


Retrofitting of RC structures:

- strengthening detail of slab with FRP

Strengthening interventions



- Scarifica e cappa integrativa
- fasce di tessuto FRP all'estradosso
- fasce di tessuto FRP all'estradosso ed all'estadosso



slab thickness = 12 cm

CIVIC THEATRE – SCHIO (VI)


Interventions

Retrofitting of RC structures:


- local FEM model



slab thickness = 10 cm



Strengthening details of the added RC slab





CIVIC THEATRE – SCHIO (VI)


Interventions

Retrofitting of RC structures:

Finite Element Model




x-x bending moment




nodal vertical displacement

slab thickness = 10 cm



Strengthening interventions




INGEGNERIA CIVILE,
EDILE E AMBIENTALE
CIVIL, ARCHITECTURAL AND
ENVIRONMENTAL ENGINEERING





CIVIC THEATRE – SCHIO (VI)

Interventions

Retrofitting of RC structures




slab thickness = 10 cm




CIVIC THEATRE – SCHIO (VI)

Interventions


Retrofitting of RC structures



slab thickness = 10 cm




Strengthening interventions



CIVIC THEATRE – SCHIO (VI)

Interventions


Retrofitting of RC structures



slab thickness = 10 cm

-  Trave rinforzata con tessuto FRP
(n° 1 strato b=10 cm)
-  Rinforzo soffitto con applicazione di fasce di tessuto FRP (n° 1 strato b=10 cm)

Strengthening interventions



THANKS FOR YOUR ATTENTION

Prof. Eng. Claudio Modena